

Coffee Scale EK6002

Operating:

- 1.) Press "ON/OFF" to display "HELLO". After stable, the display shows 0'00" 0.0g.
- 2.) Put the items on the weighing pan to weigh.
- 3.) If the display unit is not right, you can press the "UNIT" key to achieve unit conversion and select the unit you want to use.

Tare Function:

- 1.) Put a tray or container in the pan.
- 2.) Press the "TARE" key, and the display will show 0.0g.
- 3.) Then you can add items to the container or weighing plate weighing.
- 4.) When the container and contents are removed "-" will be displayed.

Timer function:

- 1.) Press the "START/STOP" key to start the timer.
- 2.) Press the "START/STOP" key once to pause the timer.
Press the "START/STOP" key again to resume the timer.
- 3.) Press and hold the "START/STOP" key will timer to zero.

Warning:

- Overweight Tip: If "EEEE" appears, do not weigh the largest range of heavy objects.
Low battery prompt: "Lo", please replace the new battery.
Unstable Tip: "unit" boot to keep the scale stable.

